		•					
	er ID 64241 aber 30, 2010 1:41:34 PM						Page 1
Item ID: Revision ID: Item Name:	D4271-011 PRELIM Fwd Beam Assembly	. 11001100	Accept .			Stop	
Start Date: Required Date: Reference:	11/30/2010 Start Qty: 1.0 12/1/2010 Req'd Qty: 1.0			Cust Item ID: Customer:	PRELIN	MINARY	ISSUE
Approvals:	Process Plan:	Date: 0 - 1 1 - 3	_	Date:		Run Star Stop	
Sequence ID/ Work Center I	Operation Description		Set Up/ Run Hours	Tool ID To	ol # Plan Ac Code Qt	cept Reject y Qty	Reject Insp. Number Stamp
Draw Nbr D4271	Revision Nbr						
100 	<b>Memo</b> 1- Pick	and Assemble as per dwg	0.00		J	S 10/12	1/01 O
110    <b>                    </b>   QC	QC5- Inspect part o	ompleteness to step on W/O	Duy	. 1 _	uarse,		
Quality Control			رح در	102/01 (10			

0.00

0.00

120

Packaging

Packaging

Identify as per dwg & Stock Location:\_\_\_\_\_

Memo

-0U

W/O:			W	ORK ORDER CHAN	IGES					
DATE	STEP	PRO	OCEDURE CHA	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					٠					
			·				-			
					i					
		***************************************		Market 1						
Part No	:	PAR #:	Fault Cat	egory:	NC	R: Yes	No <b>DQ</b>	A:	_ Date: _	
	Re	esolution:	Dispositi	on:	QA	N/C C	osed:		Date: _	
NCR:		\	WORK OR	DER NON-CONFORM	MANCE	(NCF	3)			
DATE	STEP	Description of NC	Corrective Action Section			verifica			Approval	Approval
	JILF	Section A	Initial Chief Eng	Action Description Chief Eng	n 	Date	000	ion C	Chief Eng	QC Inspector
					·					

<sup>.</sup> NOTE: Date & initial all entries

### Work Order ID 64241



Page 2

Tuesday, November 30, 2010 1:41:34 PM

Item ID:

D4271-011

**PRELIM** 

**Revision ID:** Item Name:

Fwd Beam Assembly

**Start Date:** 

**Required Date: 12/1/2010** 

11/30/2010

Start Qty: 1.00

**Req'd Qty:** 1.00

**Cust Item ID:** 

Date:

Date:

Tool # Plan

Code

**Customer:** 

Tool 1D

Reference:

Approvals:

Sequence ID/

**Work Center ID** 

Process Plan:

QC:

Operation

Description

Date:

Date:

SPC (Y/N):

**Tooling:** 

Set Up/

Run Hours

0.00

QC21- Final Inspection - Work Order Release

Memo

Accept

0.00

Quality Control

130

QC

Run

Reject

Qty

Setup Start

Start

Reject

Stop

Stop

Number Stamp

Insp.

10.12.03

Qty

Accept

POSITIVE REC

**EFFECTIVE** 

RELEAS

41.10

	-	_							
W/O:		<del></del>	W	ORK ORDER CHANG	GES	_	_		
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			-				•		
Part No	:	PAR #:	Fault Cate	egory:	NCR: Yes	s No C	DQA:	Date: _	
	Re	esolution:	Disposition	on:	QA: N/C	Closed:		Date: _	
NCR:	-		WORK ORD	ER NON-CONFORM	ANCE (NC	R)			
DATE	STEP	Description of NC			etion B	Vei	rification	Approval	Approval
	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sigr Dat	ı& ∣ <sub>S</sub>	ection C	Chief Eng	QC Inspector
_									
· -									

Tuesday, November 30, 2010 1:41:33 PM

Work Order ID: 64241

Parent Item:

D4271-011

Parent Item Name: Fwd Beam Assembly



Start Date: 11/30/2010

Required Date: 12/1/2010

Start Qty: 1.00

Required Qty: 1.00

C				4
Co	ш	ш	en	ıs:

IPP rev:A 10.11.18 new issue DD verf:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D4149-5 - PD   Byebolt Stud		Manufactured	No			100	Each	7.0000		1	0/12	/	
				Location		Loc (	Qty	Loc Code			B6	4213	12
				GA			7		<i>\rightarrow</i>			1411	
\ - \ - \ - \ - \ - \ - \					61234		7				- '		
D4274-1 - X \\		Manufactured	No			100	Each	2.0000	2 	2 45.	0/10	2/01	
				Location		Loc (	<u>Qty</u>	Loc Code			01	4210	, _
				WA			2				B6	4210	0 (24)
					63884		2		annen				
D4275-1 		Manufactured	No			100	Each	1.0000		Si	0/12	/01	
				Location		Loc C	<u>Otv</u>	Loc Code		7			
				WA			1		/_		_		
					63881		1						,
D4281-1 		Manufactured	No			100	Each	3.0000		43	(0/	2/0	/ /
-				Location		Loc C	<u>Qty</u>	Loc Code		//			
				ENG			3		_		_		
					63886		3		_				

	•							
W/O:			WO	RK ORDER CHANG	SES			
DATE	STEP	PRO	OCEDURE CHAN		Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Categ	ory:	NCR: Yes 1	lo DQA:	Date: _	
		esolution:						
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NCR)			-
DATE	STEP	Description of NC			tion B	Verification	Approval	Approval
DAIL	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
		N,			-			
	1				1		,	

Tuesday, November 30, 2010 1:41:33 PM

Work Order ID: 64241 D4271-011 Parent Item: Parent Item Name: Fwd Beam Assembly Required Date: 12/1/2010 Start Date: 11/30/2010 Start Qty: 1.00 Required Qty: 1.00 AN3C12A No 100 21.0000 Purchased Each Location Loc Qty Loc Code ST351 21 8 112314 114761 11 116022 2 MS20615-4M18 Purchased No 100 Each 357.0000 Rivet Location Loc Oty Loc Code ST323 357 152 114808 115037 205 100 1,896.000 MS21043-3 Purchased No Each Nut **Location** Loc Qty Loc Code

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC inspector			
10/0/	100	AN4C13A. M 9114615 X84 NAS1149C0432R 19114742 X168 M521043-4 1916188 X84	Ep	10/12/01	0	MIDIZE				

Part No: _	•	_PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
	Resolution:	*	Disposition:	QA: N/C Closed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B		Verification	Approval Chief Eng	Approval			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C		QC Inspecto			
					•						
				-							

#### **Picklist Print**

Tuesday, November 30, 2010 1:41:33 PM

Work Order ID: 64241

Parent Item:

D4271-011

Parent Item Name: Fwd Beam Assembly

**Start Date:** 11/30/2010

Required Date: 12/1/2010

Page 3

Start Qty: 1.00

Required Qty: 1.00

NAS1149C0332R

Purchased

No



<b>Location</b>	Loc Qty
ST297	3445
115000	125
115698	35
115832	1285
116025	2000

100

Each

Loc Code

3,445.000

	•							
W/O:			WO	RK ORDER CHANG	GES			
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date Q	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							,	
				·				
Part No	:	PAR #:	Fault Cate	jory:	NCR: Yes	No DQA: _	Date: _	
	Re	esolution:	Disposition	1;	QA: N/C CI	osed:	Date: _	
NCR:		,	WORK ORDE	R NON-CONFORM	IANCE (NCF	R)		
DATE	OTED	Description of NC			ction B	Verificati	on Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section (		QC Inspector
				·				
·	•			•	,			
	!							


PART NUMBER DESCRIPTION D4271-011 FWD BEAM ASSY D4271-013 AFT BEAM ASSY 1 D4148-3 STUD RECEIVER 1 D4148-5 EYEBOLT STUD D4149-5 EYEBOLT STUD D4274-1 PLATE, FWD SUPPORT 4 5 6 7 8 9 10 11 2 D4274-3 PLATE, AFT SUPPORT D4275-1 FWD BEAM D4276-1 AFT BEAM SPACER D4281-1 AN3C12A MS20615-4M18 BOLT RIVET 8 MS21043-3 NUT NAS1149C0332R WASHER 72 72 ANYL1357 XY XY ANDS144 CO43812 YE XE MSONO43-Y 11 12 12 9 8 PL 10 8 PL 9 12 12 11 D4271-011 FWD BEAM ASSEMBLY **D4271-013 AFT BEAM ASSEMBLY** 

					10011	1
PA1	PRELIM	IINARY		JPH	10.11.12	İ
REV.			DESCRIPTION	BY	DATE	ı
DESIG	N	JPH	DART AERO	SPACE L	TD	۱
DRAW	N	JPH	HAWKESBURY, ON	ITARIO, CANAI	DA .	l ^
CHECK	(ED	NO	DRAWING NO.		REV. BAT	10
MFG. A	PPR.	1/0	D4271		SHEET 1 OF 2	1
APPRO	VED	NI	TITLE		SCALE	l
DE APE	PR.	7,7	SUPPORT BEAM	ASSEMB	LIES NTS	l
DATE	10.1	1.12	COPYRIGHT © 2010 BY D THE DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS HOT TO BE USED FOR ANY PURPOSE OR COPED OR CO WINGTON PERMISSION FROM	SUPPLED ON THE EXPRESS CHARRESTED TO ANY OTH	S CONDITION THAT IT IS	
		1				

D

PRELIMINARY ISSUE

W/O:	<u>`</u> T		WO	RK ORDER CHAN	CEC							
DATE STEP		PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
									<u> </u>			
***************************************	-											
Part No:		PAR #:	Fault Categ	NCR:	CR: Yes No DQA: Date:							
	R	esolution:	Disposition	QA: N	/C Clo	sed:	Date: _	Date:				
NCR:		1	WORK ORDE	R NON-CONFORM	MANCE (	NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section E					ation	Approval	Approval		
			Initial Chief Eng	Action Description Chief Eng	ז ;	Sign & Date	Secti	on C	Chief Eng	QC Inspector		
•												
,	4.											
	,											



W/O:		WORK ORDER CHANGES											
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
				,									
									i				
	4												
		PAR #:	Fault Category: NC			NCR: Yes No DQA							
		esolution:	1:	QA: N/C Closed:									
NCR:			WORK ORDE	ER NON-CONFORMA	ANCE	(NCR	)						
DATE	STEP	Description of NC Section A	Corrective Action Section				Verific	ation	Approval	Approval			
			Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti		Chief Eng	QC Inspector			
					-								
								,					
			·						₹* + <b>\$</b> ;:				
							1						

